

Seawater Access System Photo Log



Photo 1: Upland route looking east over the “horseback” roadway zone at the Eckrote property



Photo 2: Intertidal mud flats from the Eckrote property shore.



Photo 3: Example of a narrow sheet pile structure with struts to suit this type of work.



Photo 4: Example of a shoreline coffer cell and excavator on the mudflats.




Photo 5: Example of a spud barge with crane, clamshell suited for this work.